

## 014050 RRDE-3A/CS-3A gas purge tube repair kit


Thank you for your purchase from BAS Inc.

This product is a tube repair kit for RRDE-3A Rotating Ring Disk Electrode Apparatus or CS-3A Cell Stand.

Please check the detailed instructions for tube replacement on our website below before proceeding.

<https://www.als-japan.com/support-instrument-manual.html>


### Contents




- |   |      |
|---|------|
| (A) Silicone tube                                     | 1 pc |
| (B) Silicone tube + Teflon tube<br>(with black cover) | 1 pc |
| (C) Silicone tube + Teflon tube                       | 1 pc |

※Please turn off the power and unplug the power cable before performing replacement.

### RRDE-3A piping tube replacement



### CS-3A piping tube replacement



- (A): Tube from gas inlet connector to needle valve
- (B): Purge tubes from the needle valve through the pinch valve (with black cover)
- (B): Purge tubes from the needle valve through the pinch valve

#### • Relative Product

012779 CS-3A Cell Stand Ver.1.1

013725 RRDE-3A Rotating Ring Disk Electrode Apparatus Ver.3.0

Previous product

RRDE-3A Rotating Ring Disk Electrode Apparatus Ver.2.0

BAS Inc.

<https://www.als-japan.com>

email: [sales@als-japan.com](mailto:sales@als-japan.com)